## **Government Estimate**

Item		Description	Qty	Each	Total
1	В	Utility Upgrade	1	\$0.00	\$757,006.00
2	В	Asbestos and Lead Based	1	\$0.00	\$128,967.00
				*****	\$885,973.00
3	0	Repair Building 50208	1	\$0.00	\$910,500.00
4	0	Repair Hangar 50207	1	\$0.00	\$582,517.00
5	0	Floor Coating Hangar 50207	1	\$0.00	\$46,469.00
6	0	Repair Hangar 50209	1	\$0.00	\$565,811.00
7	0	Floor Coating Hangar 50209	1	\$0.00	\$46,469.00
8	0	Administration Office/Restroom	1	\$0.00	\$24,729.00
9	0	Elevator/Lift, Building 50208	1	\$0.00	\$39,066.00
		•			\$2,215,561.00
Ande	rson (	Construction Company of Fo, P. O. Box 220, Fort Gaines, GA 31751, 229	-768-2555		
Item		Description	Qty	Each	Total
1	В	Utility Upgrade	1	\$0.00	\$623,123.00
2	В	Asbestos and Lead Based	1	\$0.00	\$300,438.00
				,	\$923,561.00
3	0	Repair Building 50208	1	\$0.00	\$938,085.00
4	0	Repair Hangar 50207	1	\$0.00	\$463,161.00
5	0	Floor Coating Hangar 50207	1	\$0.00	\$20,611.00
6	0	Repair Hangar 50209	1	\$0.00	\$562,861.00
7	0	Floor Coating Hangar 50209	1	\$0.00	\$20,611.00
8	0	Administration Office/Restroom	1	\$0.00	\$51,295.00
9	0	Elevator/Lift, Building 50208	1	\$0.00	\$54,443.00
		•			\$2,111,067.00
Jime	nez, Ir	nc., P.O. Box 50395, Mobile, AL 36605-0395, 251-476-7038			
ltem		Description	Qty	Each	Total
<b>Item</b> 1	В	<b>Description</b> Utility Upgrade	<b>Qty</b> 1	<b>Each</b> \$0.00	
	B B	Description Utility Upgrade Asbestos and Lead Based	_	\$0.00	<b>Total</b> \$515,536.28 \$212,882.80
1		Utility Upgrade	1		\$515,536.28
1		Utility Upgrade	1	\$0.00	\$515,536.28 \$212,882.80
1 2	В	Utility Upgrade Asbestos and Lead Based	1	\$0.00 \$0.00	\$515,536.28 \$212,882.80 <b>\$728,419.08</b>
1 2 3	В О	Utility Upgrade Asbestos and Lead Based Repair Building 50208	1	\$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 <b>\$728,419.08</b> \$1,149,566.42
1 2 3 4	В О О	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207	1 1 1	\$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 <b>\$728,419.08</b> \$1,149,566.42 \$542,046.52
1 2 3 4 5	B O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207	1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 <b>\$728,419.08</b> \$1,149,566.42 \$542,046.52 \$50,779.31
1 2 3 4 5 6	B O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209	1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 <b>\$728,419.08</b> \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42
1 2 3 4 5 6 7	B O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209	1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 <b>\$728,419.08</b> \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10
1 2 3 4 5 6 7 8	B O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom	1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$ <b>728,419.08</b> \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04
1 2 3 4 5 6 7 8 9	B O O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom	1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 <b>\$728,419.08</b> \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18
1 2 3 4 5 6 7 8 9	B O O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208	1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 <b>\$728,419.08</b> \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18
1 2 3 4 5 6 7 8 9	B O O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208	1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99
1 2 3 4 5 6 7 8 9 Glob	B O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  Instruction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description	1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99
1 2 3 4 5 6 7 8 9 Globo	B O O O O O O O O B	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  struction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description Utility Upgrade	1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99
1 2 3 4 5 6 7 8 9 Globo	B O O O O O O O O B	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  struction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description Utility Upgrade	1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$ <b>728,419.08</b> \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$ <b>2,351,214.99</b> <b>Total</b> \$476,140.00 \$195,400.00
1 2 3 4 5 6 7 8 9 Globb Item 1 2	B O O O O O O B B B	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  struction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description Utility Upgrade Asbestos and Lead Based	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99 Total \$476,140.00 \$195,400.00 \$671,540.00
1 2 3 4 5 6 7 8 9 Globo Item 1 2 3	B O O O O O O B B B	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  struction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description Utility Upgrade Asbestos and Lead Based  Repair Building 50208	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99 Total \$476,140.00 \$195,400.00 \$671,540.00 \$829,450.00
1 2 3 4 5 6 7 8 9 Glob Item 1 2 3 4	B O O O O O O O O O O O O O O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  Astruction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description Utility Upgrade Asbestos and Lead Based  Repair Building 50208  Repair Hangar 50207	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99 Total \$476,140.00 \$195,400.00 \$671,540.00 \$829,450.00 \$508,000.00
3 4 5 6 7 8 9 Globb  Item 1 2 3 4 5 5	B O O O O O O O O O O O O O O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  struction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description Utility Upgrade Asbestos and Lead Based  Repair Building 50208  Repair Hangar 50207 Floor Coating Hangar 50207	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99 Total \$476,140.00 \$195,400.00 \$671,540.00 \$829,450.00 \$508,000.00 \$28,400.00
3 4 5 6 7 8 9 Globb 1tem 1 2 3 4 5 6	B O O O O O O O O O O O O O O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  struction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99 Total \$476,140.00 \$195,400.00 \$671,540.00 \$829,450.00 \$508,000.00 \$28,400.00 \$493,000.00
3 4 5 6 7 8 9 Globb 1tem 1 2 3 4 5 6 7 7	B O O O O O O O O O O O O O O O O O O O	Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209 Administration Office/Restroom Elevator/Lift, Building 50208  struction Managers, Inc, P.O. Box 2109, Sanford, FL 32772, 407-302-304  Description Utility Upgrade Asbestos and Lead Based  Repair Building 50208 Repair Hangar 50207 Floor Coating Hangar 50207 Repair Hangar 50209 Floor Coating Hangar 50209	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$515,536.28 \$212,882.80 \$728,419.08 \$1,149,566.42 \$542,046.52 \$50,779.31 \$458,403.42 \$55,258.10 \$36,794.04 \$58,367.18 \$2,351,214.99 Total \$476,140.00 \$195,400.00 \$671,540.00 \$829,450.00 \$508,000.00 \$28,400.00 \$28,400.00

## Whitesell-Green, Inc., P.O. Box 2849, Pensacola, FL 32513-0849, 850-434-5311

Item		Description	Qty	Each	Total
1	В	Utility Upgrade	1	\$0.00	\$512,000.00
2	В	Asbestos and Lead Based	1	\$0.00	\$122,000.00
					\$634,000.00
3	0	Repair Building 50208	1	\$0.00	\$975,000.00
4	0	Repair Hangar 50207	1	\$0.00	\$495,000.00
5	0	Floor Coating Hangar 50207	1	\$0.00	\$24,800.00
6	0	Repair Hangar 50209	1	\$0.00	\$482,000.00
7	0	Floor Coating Hangar 50209	1	\$0.00	\$24,800.00
8	0	Administration Office/Restroom	1	\$0.00	\$42,000.00
9	0	Elevator/Lift, Building 50208	1	\$0.00	\$52,000.00
		,		,	\$2,095,600.00
Spee	egle Co	onstruction, Inc., P.O. Box 1325, Niceville, FL 32588, 850-729-2484			
Item		Description	Qty	Each	Total
1	В	Utility Upgrade	1	\$0.00	\$577,000.00
2	В	Asbestos and Lead Based	1	\$0.00	\$79,000.00
_		Albertos and Esad Based	•	ψ0.00	\$656,000.00
0	_	Daniela Dallulla in F0000		<b>#0.00</b>	
3	0	Repair Building 50208	1	\$0.00	\$871,000.00
4	0	Repair Hangar 50207	1	\$0.00	\$447,000.00
5	0	Floor Coating Hangar 50207	1	\$0.00	\$27,000.00
6	0	Repair Hangar 50209	1	\$0.00	\$471,000.00
7	0	Floor Coating Hangar 50209	1	\$0.00	\$27,000.00
8	0	Administration Office/Restroom	1	\$0.00	\$47,000.00
9	0	Elevator/Lift, Building 50208	1	\$0.00	\$57,000.00
					\$1,947,000.00
Greg	Cons	truction Co., 210 West College St., Ozark, AL 36360, 334-445-3656			
Item		Description	Qty	Each	Total
1	В	Utility Upgrade	1	\$0.00	\$780,622.00
2	В	Asbestos and Lead Based	1	\$0.00	\$13,337.00
					\$793,959.00
3	0	Repair Building 50208	1	\$0.00	\$943,258.00
4	0	Repair Hangar 50207	1	\$0.00	\$496,103.00
5	0	Floor Coating Hangar 50207	1	\$0.00	\$21,452.00
6	0	Repair Hangar 50209	1	\$0.00	\$641,399.00
7	0	Floor Coating Hangar 50209	1	\$0.00	\$21,452.00
8	0	Administration Office/Restroom	1	\$0.00	\$51,203.00
9	0	Elevator/Lift, Building 50208	1	\$0.00	\$2,667.00
					\$2,177,534.00
C & D Construction, Inc., P.O. Box 1626, Cocoa, FL 32923-1626, 321-639-9198					
Item		Description	Qty	Each	Total
1	В	Utility Upgrade	1	\$0.00	\$835,000.00
2	В	Asbestos and Lead Based	1	\$0.00	\$164,000.00
					\$999,000.00
3	0	Repair Building 50208	1	\$0.00	\$1,037,000.00
4	0	Repair Hangar 50207	1	\$0.00	\$456,000.00
5	0	Floor Coating Hangar 50207	1	\$0.00	\$21,990.00
6	0	Repair Hangar 50209	1	\$0.00	\$699,000.00
7	0	Floor Coating Hangar 50209	1	\$0.00	\$21,990.00
8	0	Administration Office/Restroom	1	\$0.00	\$48,000.00
9	0	Elevator/Lift, Building 50208	1	\$0.00	\$45,000.00
-	-	. , <del>.</del>		, J	\$2,328,980.00
					, ,,

## Cedars Electro-Mechanical Inc, 1712 South Dixie Highway, Lake Worth, FL 33460, 561-588-4088

Item		Description	Qty	Each	Total
1	В	Utility Upgrade	1	\$0.00	\$573,973.00
2	В	Asbestos and Lead Based	1	\$0.00	\$250,000.00
					\$823,973.00
3	0	Repair Building 50208	1	\$0.00	\$850,000.00
4	0	Repair Hangar 50207	1	\$0.00	\$525,000.00
5	0	Floor Coating Hangar 50207	1	\$0.00	\$25,000.00
6	0	Repair Hangar 50209	1	\$0.00	\$425,000.00
7	0	Floor Coating Hangar 50209	1	\$0.00	\$15,000.00
8	0	Administration Office/Restroom	1	\$0.00	\$30,000.00
9	0	Elevator/Lift, Building 50208	1	\$0.00	\$55,000.00
					\$1.925.000.00

## Sauer Incorporated d/b/a Sauer Southeast, 11223 Phillips Parkway Drive East, Jacksonville, FL 32256, 904-262-6444

Item		Description	Qty	Each	Total
1	В	Utility Upgrade	1	\$0.00	\$944,000.00
2	В	Asbestos and Lead Based	1	\$0.00	\$199,000.00
					\$1,143,000.00
3	0	Repair Building 50208	1	\$0.00	\$965,000.00
4	0	Repair Hangar 50207	1	\$0.00	\$531,000.00
5	0	Floor Coating Hangar 50207	1	\$0.00	\$38,000.00
6	0	Repair Hangar 50209	1	\$0.00	\$875,000.00
7	0	Floor Coating Hangar 50209	1	\$0.00	\$327,000.00
8	0	Administration Office/Restroom	1	\$0.00	\$54,000.00
9	0	Elevator/Lift, Building 50208	1	\$0.00	\$52,000.00
					\$2,842,000.00